



# Kitchen Fire

Back Open In 48 Hours

Wednesday, October 15, 2014

Mickey Perritt

Century Services

Taken 19 Photos



Issue

### Photo 1

Comments

Small fire behind flattop.

Fire department chopped through wall to insure fire did not hide from them.



Issue

### Photo 2

Comments

Another view of effected area.



Issue

### Photo 3

Comments

The fire was pretty hot.



Issue

### Photo 4

Comments

The gas flex hose was leaking. This is where the fire started.



Issue

### Photo 5

Comments

The guilty party! Gas flex leaked and started the fire.



Issue

### Photo 6

Comments

Flames ran under table and escaped up under shelf.



Issue

**Photo 7**

Comments

**Ansul dumped.**



Issue

**Photo 8**

Comments

**Ansul dumps and makes a huge mess.**



Issue

**Photo 9**

Comments

**More of the mess.**




Issue

### Photo 10

Comments

Started defacing the damaged wall searching for damage.



Issue

### Photo 11

Comments

Frp on wall to be removed.



Issue

### Photo 12

Comments

Fire inspector wants FRP replaced with stainless steel.





Issue

### Photo 13

Comments

Wall opened up and defaced. No damage inside wall.

Have to get inspection before closing up wall.




Issue

### Photo 14

Comments

Got the approval to close up the wall.

Replaced the plywood with concrete board. Fire caulked all seams and openings in wall.



Issue

### Photo 15

Comments

New stainless steel wall panel up and in place.



Issue

## Photo 16

Comments

New stainless steel wall panels installed.



Issue

## Photo 17

Comments

Ceiling repaired, new outlets in ready for final inspection.



Issue

## Photo 18

Comments

Passed inspection. Finish setting equipment in place. Store ready to open.



Issue

**Photo 19**

Comments

**Job complete, store ready to open.**