



Friday's DFW E-17

Water Leak Through Floor

Wednesday, December 10, 2014

Taken 16 Photos

Mickey Perritt
Century Services



Photo 1

Water leak below floor is coming through two (2) pipe penetrations in the wall to the right of the water heater.



Photo 2

There is some standing water along wall under the water heater. The grout is low under the water heater but we cannot reach it to regroup it.



Photo 3

The water in the wall track can be seen in the access door.



Photo 4

Looking down inside the wall through the access door you can see about 1/4" to 1/2" of standing water.



Photo 5

There is a little standing water in the grout joints under the water heater.



Photo 6

The wall adjacent to the water heater where the grease barrels are kept has most of the base tile broke out of the wall. This is about 5' of wall.



Photo 7

More of the damaged wall behind the grease barrels.



Photo 8

Pulled water heater, removed tile base and tile at floor.



Photo 9

Wall where water was leaking through floor.



Photo 10

New stainless base pollyurthaned in place.



Photo 11

New base set and sealed.




Photo 12

Base set starting to lay new tile.



Photo 13

New tile laid and grouted.



Photo 14

Water heater set back into place.



Photo 15

Job complete.



Photo 16
Job complete.