

WALK IN COOLER FLOOR REPLACEMENT.

Wednesday, June 4, 2014

Taken 12 Photos

Mickey Perritt
Century Services





Photo 1

The before. Floor damaged by beer kegs being dropped on it.



Photo 2

All empty, let's get this thing out of here.




Photo 3

Pulling old floor.



Photo 4

Old floor out. Now let's get this cleaned up and sanitized.




Photo 5

Alright, cleaned up! Now let's get the new floor down.




Photo 6

Installing 16 ga stainless steel strips. Set with polyurethane and pop rivets.



Photo 7

More strips.




Photo 8

New 3/16" diamond plate set on strips with polyurethane to keep water and moisture out from under floor. Secured with stainless steel pop rivets.




Photo 9

Securing new floor.



Photo 10

New floor in. Seams kept under shelves to minimize seams in walk area.



Photo 11

Finished floor.



Photo 12

Everything back in the walk in.